Notice



ATION FILE NO.	
ON 0	
ER / 01 / 2011	
12861-10	
in the Service	
ditional Service	

SERVICING SHOULD BE PERFORMED BY ONLY TRAINED AND QUALIFIED SERVICE PERSONNEL.

difference Service Information is given in this manual. For detailed Service Information, refer to the **Original** Service Manual and **Notices** for Chassis No. P42841-10 used in

1. IN THE SERVICE ADJUSTMENTS

Model DP42841 (SM780194).

The are no changes.

2. IN THE CHASSIS ELECTRICAL PARTS LIST MISCELLANEOUS

The are no changes.

For parts or service contact:

Sanyo Manufacturing Corporation P.O. Box 2000 3333 Sanyo Road Forrest City, Arkansas 72335-2000

November 2011 SMC

Sanyo Manufacturing Corporation 2011